

Selfeeder Varimec Selfeeder Mechatric **CNC Turret Head**



http://www.sugino.com

1-9-13, Nihonbashi-Honcho, Chuo-ku, Tokyo, 103-0023 JAPAN ☎+81-3-5201-5974 FAX+81-3-5201-5978 e-mail:export@sugino.com

•	~…
Overseas	Office

☎+1-630-250-8585 FAX +1-630-250-8665 e-mail:mach@suginocorp.com Sugino Corp.

Sugino Machine Mexico, S.A. DE C.V. \$\oldsymbol{\pi}\$+52-81-1100-0108 FAX+52-81-1100-0318 Mexico

China

Sugino Shanghai Co.,Ltd.

Shanghai office

☎+86-21-5385-5031 FAX +86-21-5385-5032 e-mail:sh@sugino.cn ☎+86-20-8363-4719 FAX +86-20-8363-4992

Sugino Machine (Thailand) Ltd.

FAX +66-3572-9355 e-mail:contact@sugino.th.com FAX +65-6456-7789

Czech

Praha, Branch Office

Sugino Machine Singapore Pte. Ltd. **☎**+65-6458-9544

☎+66-3572-9351

e-mail:ventas@sugino.com.mx

e-mail:sales@sugino-singapore.com.sg ☎+420-257-950-228 FAX +420-257-950-044

e-mail:info@sugino.cz



 $\label{eq:specifications} \ensuremath{\mathrm{\%}}\xspace \ensuremath{\mathrm{Specifications}}\xspace \ensuremath{\mathrm{in}}\xspace \ensuremath{\mathrm{this}}\xspace \ensuremath{\mathrm{catalogue}}\xspace \ensuremath{\mathrm{guess}}\xspace \ensuremath{\mathrm{arg}}\xspace \ensuremath{\mathrm{this}}\xspace \ensuremath{\mathrm{catalogue}}\xspace \e$

Features of

Selfeeder

Servo series

Highly rigid and long stroke(up to 300mm) drill unit with compact size. Variety of models available for wide ranges of machining requirements.



eliminated by the precise angular bearing supporting spindle and the high quality ball screw. As the result the generation of burr is reduced and the tool life is longer.




A newly developed structure holds the spindle ball screw and linear guide making the drill unit body rigid and strong enough to step spot face and burnish drilling. (JP PAT.)



Selfeeder Varimec

A new generation model of Selfeeder Mechatric that has high rigidity to make a high performance with compact body.






Aluminium $\phi 8.5$ $\phi 6$	
Aluminium Sto φ12 φ	
Aluminium Sto	
Aluminium Sto	

Selfeeder Mechatric

Multi functionable basic unit featured with higher torque for large hole drilling and coolant center through etc.



	φ 16	ø11	SSM4	12 _p
	Aluminium $\phi 24$	Steel ϕ 19	SSM5·····	14 p
1	Aluminium φ14	Steel $\phi 10$	MS3P ·····	16 _p
	Aluminium $\phi 40$	Steel φ 28	MS7	17p

CNC Turret Head

High-efficient model for intensive production to be capable for 4 different operations with single unit that is flexible for installation for new line as well as existing line as it is unit type.



Aluminium $\phi 12$	Steel $\phi 8$	4TH3S ····	18 _p
Aluminium φ20	Steel $\phi 13$		00
Aluminium M16	Steel M12	4TH5	20 p

22.23_p

Data input system / other attachments

Programming console, Touch panel, Computer monitoring software, Process patterns Varimotor, Standrill NC

High-efficient deep hole drilling

Coolant center through type (Max. 6.8MPa) is available for Mechatric series for efficient deep hole drilling by oil hole drill tool.



Spindle rotation speed is variable by attached inverter.

Optimize speeds to adapt to different

Optimize speeds to adapt to different cutting requirements.



Easy operation

5.7inch touch panel type color display (liquid crystal) makes it easy to make a CNC program and operate even for a beginner operator. Four different languages are available for the oversea usage.



Max. Drilling size (mm)

Selfeeder Varimec









The smallest model of Varimec utilizes a high-performance motor (high-speed and high-power) into a small, compact sized body. It provides high performance for production of small parts and small-diameter drilling.


Specification Chart

Specs.	Spindle speed (no load)	Chuck type	Chucking	Max.	Drilling	size		Spindle	Feed		Rapid	Cutting	
	50Hz 60Hz	(Collet chuck)	capacity	AL* (ADC)	FC* (FC200)	ST* (S45C)	Stroke	motor	motor	Thrust	approach speed	Cutting speed	Weight
Model	min ⁻¹	_	mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	kg
SSV2-7200	2,000~ 20,000	ER11MS	0.5~7.0	5	4	3,5	Max.	0.9 15,000min ⁻¹ /hr.	0.4 AC	1,200	Max.	Max.	15
SSV2-1039	390~ 3,900	ER16	0.5~10.0	8.5	7.5	6.5	80	DC brushless motor	servo motor	1,200	200	16.7	15

Notes 1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

- The drilling capacity shown above is for a depth equivalent to the drill diameter times two.
 The power voltage of the main spindle inverter is a 3-phase 200V AC±10%, 50/60Hz. (Feeding axis controller is single-phase.)
- In the case of a servo motor with a holding brake (optional), add "B" to the end of the model number
 AL*...Aluminium, FC*...Cast Iron, ST*...Steel

Dimensions (mm)




Note: Air must be supplied to cool the spindle motor as to protect the spindle bearings. Be sure to supply clean dry air.

Adjustable spindle nose (option)

Please specify the adjustable spindle nose when ordering your servo drill.

Sugino supplies adjustable spindle noses other than those shown below, upon request.


Applicable selfeeder	Fig. No.	Spindle nose model No.
SSV2-7200	1	KH-12E
SSV2-1039	2	KH-14E



Notes 1. Spindle noses KH-E model are applicable to the quick change stub holder of KH-A or KH-E model of NT Tool Co.,Ltd. 2. Quick change stub holder can not use in over 15,000min⁻¹ spindle speed operation

Electric system diagram

All the electric parts supplied as standard are indicated in The purchaser is responsible for and needs to have the other cables and equipment.




Notes1. The feed controller and the spindle inverter are standard accessories.

- 2. The programming console and touch panel is optionally available. The attached cable is 3m long.
- 3. Programming from a computer is possible using a ® PC cable A. In such case, a dedicated computer monitoring software is required Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port.

Controller for feed motor UC-81A Dimensions(mm) W85.5×D168×H225 Weight/2.1kg

Inverter	for	spindle	motor	UC-93
----------	-----	---------	-------	-------



Specification of signal

1/0	Signal	Contents		
Analog	ORD	Command for spindle speed		
Output	СОМ	Ground of command for spindle speed		
	INO	Emergency stop		
	IN1	Manual coolant ON/OFF		
	IN2	Power "ON"		
	IN3	Machine zero return		
	IN4	Single step		
	IN5	Spindle alarm		
	IN6	JOG+		
	IN7	JOG-		
	IN8	Forward side OT		
	IN9	Backward side OT (Combine with origin LS)		
 * 1	NC	No contact terminal		
Input	IN10	Alarm clear		
	IN11	EXT/MANUAL		
	IN12	Manual spindle ON/OFF		
	IN13	Program 1		
	IN14	Program 2		
	IN15	Program 4		
	IN16	Program 8		
	IN17	Program 10		
	IN18	Program 20		
	IN19	Program 40		

1/0	Signal	Contents	
	OUT0	RDY	
	OUT1	Cycle run	
	OUT2	Program end	
	OUT3	Origin	
#2 Output	OUT4	Spindle ON	
Output	OUT5	Ready for single step	
	OUT6	Coolant ON	
	OUT7	Forward sideON	
	OUT8	Alarm	

*1 Voltage: DC24V, Electric current: 10mA ※2 Voltage: DC24V, Electric current: 90mA

Selfeeder Varimec








Short length, compact sized unit capable to drill small diameter and deep holes. Well suited unit for designing/producing low cost and flexible drilling machine.

Specification Chart

Specs.	Spindle speed (no lo	Chuck type	Chucking	Max.	Drilling			Spindle	Feed		Rapid	Cutting	
	50Hz 60H	(Collet chuck)	capacity	AL* (ADC)	FC* (FC200)	ST* (S45C)	Stroke	motor	motor	Thrust	approach speed	Cutting speed	Weight
Model	min-1		mm	mm	mm	mm	mm	kW	kW	Ν	mm/sec	mm/sec	kg
SSV3-7100	1,000~	ER11	0.5~7.0	6.5	5	4							
3373-7100	10,000	ER20	0.5~13.0	0.5	3	.7	Max.	0.4 DC	0.4 AC	1.660	Max.	Max.	43
SSV3-1626	265~	ER20	0.5~13.0	12	9	8	200	brushless motor	servo motor	1,000	200	16.7	43
3373-1020	2,650	ER25	0.5~16.0	12	9	0							

Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

- 2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.
- 3. The power voltage of the main spindle inverter is a 3-phase 200V AC±10%, 50/60Hz. (Feeding axis controller is single-phase.)
- 4. In the case of a servo motor with a holding brake (optional), add "B" to the end of the model number 5. AL*...Aluminium, FC*...Cast Iron, ST*...Steel




Note: Air must be supplied to cool the spindle motor as to protect the spindle bearings. Be sure to supply clean dry air.

Adjustable spindle nose (option)

Please specify the adjustable spindle nose when ordering your servo drill.

Sugino supplies adjustable spindle noses other than those shown below, upon request.


Applicable selfeeder	Fig. No.	Spindle nose model No.
SSV3-7100	1	KH-14AR
SSV3-1626	2	KH-25A



Notes: Spindle noses KH-A model is applicable to the quick change stub holder of KH-A model of NT Tool Co.,Ltd.

Electric system diagram


All the electric parts supplied as standard are indicated in The purchaser is responsible for and needs to have the other cables and equipment.




Notes1. The feed controller and the spindle inverter are standard accessories.

- 2. The programming console and touch panel is optionally available. The attached cable is 3m long.
- 3. Programming from a computer is possible using a ⁽¹⁾ PC cable A. In such case, a dedicated computer monitoring software is required.
- Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port

Controller for feed motor UC-81A



Inverter for spindle motor MVX103BVC



Specification of signal

1/0	Signal	Contents		
Analog	ORD	Command for spindle speed		
Output	СОМ	Ground of command for spindle speed		
	INO	Emergency stop		
	IN1	Manual coolant ON/OFF		
	IN2	Power "ON"		
	IN3	Machine zero return		
	IN4	Single step		
	IN5	Spindle alarm		
	IN6	JOG+		
	IN7	JOG-		
	IN8	Forward side OT		
	IN9	Backward side OT (Combine with origin LS)		
*1	NC	No contact terminal		
Input	IN10	Alarm clear		
	IN11	EXT/MANUAL		
	IN12	Manual spindle ON/OFF		
	IN13	Program 1		
	IN14	Program 2		
	IN15	Program 4		
	IN16	Program 8		
_	IN17	Program 10		
	IN18	Program 20		
	IN19	Program 40		
	TALOO	Drogram 90		

1/0	Signal	Contents
	OUT0	RDY
	OUT1	Cycle run
	OUT2	Program end
	OUT3	Origin
#2 Output	OUT4	Spindle ON
Output	OUT5	Ready for single step
	OUT6	Coolant ON
	OUT7	Forward sideON
	OUT8	Alarm

¾1 Voltage: DC24V, Electric current: 10mA #2 Voltage: DC24V, Electric current: 90mA

Dimensions(mm)

Fig. 1 KH-22A

Fig. 2 KH-32A

Notes: Spindle noses KH-A model is applicable to the quick change stub holder of KH-A model of NT Tool Co., Ltd.

All the electric parts supplied as standard are indicated in ______ box.

The purchaser is responsible for and needs to have the other cables and equipment.

Electric system diagram

Adjustable spindle nose (option)

Please specify the adjustable spindle nose

Sugino supplies adjustable spindle noses other than those shown below, upon request.

Applicable selfeeder Fig. No. Spindle nose model No.


KH-22A

KH-32A

when ordering your servo drill.

SSV4-2070


SSV4-2017




Notes1. The feed controller and the spindle inverter are standard accessories.

- 2. The programming console and touch panel is optionally available. The attached cable is 3m long.
- 3. Programming from a computer is possible using a ® PC cable A. In such case, a dedicated computer monitoring software is required. Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port.

Controller for feed motor UC-82



Inverter for spindle motor UC-92



Analog	ORD	Command for spindle speed
Output	COM	Ground of command for spindle speed
	INO	Emergency stop
	IN1	Manual coolant ON/OFF
	IN2	Power "ON"
	IN3	Machine zero return
	IN4	Single step
	IN5	Spindle alarm
	IN6	JOG+
	IN7	JOG-
	IN8	Forward side OT
	IN9	Backward side OT (Combine with origin LS)
*1	NC	No contact terminal
Input	IN10	Alarm clear
	IN11	EXT/MANUAL
	IN12	Manual spindle ON/OFF
	IN13	Program 1
	IN14	Program 2
	IN15	Program 4
	IN16	Program 8
	IN17	Program 10
	IN18	Program 20

IN19

Specification of signal

Contents

Program 40

Signal

1/0	Signal	Contents
	OUT0	RDY
	OUT1	Cycle run
	OUT2	Program end
	OUT3	Origin
#2 Output	OUT4	Spindle ON
Output	OUT5	Ready for single step
	OUT6	Coolant ON
	OUT7	Forward sideON
	OUT8	Alarm

¾1 Voltage: DC24V. Electric current: 10mA #2 Voltage: DC24V, Electric current: 90mA

Selfeeder Varimec

Model which has most suitable body structure for doing stepped spot-facing or burnishing drill operations.

Also it is possible to do more high-efficient processing when you use this drill unit with multi-spindle heads.

■ Specification Chart

					_										
	Specs.	Spindle spe	ed (no load)	Chuck type	Chucking	Max.	Drilling	size	(. in)	Spindle	Feed	ALC: H	Rapid	Cutting	
		50Hz	60Hz	(Collet chuck)	capacity		FC* (FC200)	ST* (S45C)	Stroke	motor	motor	Thrust	approach speed	Cutting speed	Weight
Мо	del	mi	n ⁻¹		mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	kg
S	SV4-2070	1,000 7	0~ ,000	ER32	1.0~20.0	9	8	7	Max.	1.0 DC brushless	1.2 AC	4.600	Max.	Max.	80
S	SV4-2017	250~ 1	,750	ER32	1.0~20.0	16	15	13	250	motor	servo motor	4,600	220	16.7	80


Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.

- 3. The power voltage of the feed controller and main spindle inverter is a 3-phase 200V AC±10%, 50/60Hz.

 4. In the case of a servo motor with a holding brake (optional), add "B" to the end of the model number.
- 5. AL*...Aluminium, FC*...Cast Iron, ST*...Stee

Dimensions (mm)



Notes1. In the case of a servo motor with a holding brake (optional), the dimension of the feed motor is different.

2. Air must be supplied to cool the spindle motor as to protect the spindle bearings. Be sure to supply clean dry air

Selfeeder Varimec









High-power model which has 1.6kW spindle motor and 7,700N thrust. It is capable of end-mill, facing or 28mm diameter drilling operations into steel material utilizing a unique linear guide system (JP PAT.).

Specification Chart

Specs.	Spindle speed (no load)	Chuck type	Chucking	Max.	Drilling	size		Spindle	Feed		Rapid	Cutting	
	50Hz 60Hz	(Collet chuck)	capacity	AL* (ADC)	FC* (FC200)	0.	Stroke	motor	motor	Thrust	approach speed	speed	Weight
Model	min ⁻¹		mm	mm	mm	mm	mm	kW	kW	Ν	mm/sec	mm/sec	kg
SSV5-2055	800~ 5,500	ER32	1.0~20.0	14.5	11.5	9.5	Max.	1.6 DC brushless	2.7 AC	7.760	Max.	Max.	100
SSV5-2610	150~ 1,010	ER40	2.0~26.0	25	20.5	18	300	motor	servo motor	7,760	300	16.7	100


- Notes 1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

 2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.

 - 3. The power voltage of the feed controller and main spindle inverter is a 3-phase 200V AC±10%, 50/60Hz.

 4. In the case of a servo motor with a holding brake (optional), add "B" to the end of the model number.
 - 5. AL*···Aluminium, FC*···Cast Iron, ST*···Stee

Dimensions (mm)



Notes 1. In the case of a servo motor with a holding brake (optional), the dimension of the feed motor is different.


2. Air must be supplied to cool the spindle motor as to protect the spindle bearings. Be sure to supply clean dry air

Adjustable spindle nose (option)

Please specify the adjustable spindle nose when ordering your servo drill.

Sugino supplies adjustable spindle noses other than those shown below, upon request.

Applicable selfeeder	Fig. No.	Spindle nose model No.
SSV5-2055	1	KH-32A
SSV5-2610		NH-3ZA




Notes: Spindle noses KH-A model is applicable to the quick change stub holder of KH-A model of NT Tool Co.,Ltd.

Electric system diagram


All the electric parts supplied as standard are indicated in box.

The purchaser is responsible for and needs to have the other cables and equipment.




- 2. The programming console and touch panel is optionally available. The attached cable is 3m long
- 3. Programming from a computer is possible using a [®] PC cable A. In such case, a dedicated computer monitoring software is required. Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port.

Controller for feed motor UC-83A



Inverter for spindle motor E100-075LFR2



Specification of signal

1/0	Signal	Contents			
Analog	ORD	Command for spindle speed			
Output	СОМ	Ground of command for spindle speed			
	INO	Emergency stop			
	IN1	Manual coolant ON/OFF			
	IN2	Power "ON"			
	IN3	Machine zero return			
	IN4	Single step			
	IN5	Spindle alarm			
	IN6	JOG+			
	IN7	JOG-			
	IN8	Forward side OT			
	IN9	Backward side OT (Combine with origin LS)			
 #1	NC	No contact terminal			
Input	IN10	Alarm clear			
	IN11	EXT/MANUAL			
	IN12	Manual spindle ON/OFF			
	IN13	Program 1			
	IN14	Program 2			
	IN15	Program 4			
	IN16	Program 8			
name d	IN17	Program 10			
arres a	IN18	Program 20			
	IN19	Program 40			

ai		
1/0	Signal	Contents
	OUT0	RDY
	OUT1	Cycle run
	OUT2	Program end
	OUT3	Origin
#2 Output	OUT4	Spindle ON
Output	OUT5	Ready for single step
	OUT6	Coolant ON
	OUT7	Forward sideON
	OUT8	Alarm

*1 Voltage: DC24V, Electric current: 10mA ※2 Voltage: DC24V. Electric current: 90mA

Selfeeder Mechatric



SCICCO SERVO series





Most suitable unit for doing small diameter and deep hole drilling. The spindle rotation speed is easily adjusted in the program. It can utilize coolant center-through tooling specification as an option for doing more high-efficient processing.

Specification Chart

Specs.	Spindle spe	ed (no load)	Chuck type	Chucking	Max.	Drilling	size		Spindle	Feed	TA:	Rapid	Cutting	
	50Hz		(Collet chuck)		AL* (ADC)	FC* (FC200)	01	Stroke	motor	motor	Thrust	approach speed	Cutting speed	Weight
Model	mi	n ⁻¹	-	mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	kg
SSM4-1673	1,470~	7,320			6	5	4		0.75 DC brushless motor					
SSM4-1636	720~	3,600	ER25	0.5~16	8	7	.6	Max.	Rated speed 3,600min ⁻¹	0.4 AC	2,320	Max.	Max.	60
SSM4-1618	360~	1,800		0.5~16	11	9	8	150	0.75 DC brushless motor	servo motor	2,320	150	16.7	60
SSM4-1608	180~	- 880	5		16	12	11		Rated speed 1,800min ⁻¹					


Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.

3. The power voltage of the main spindle inverter is a 3-phase 200V AC±10%, 50/60Hz. (Feeding axis controller is single-phase.) 4. In the case of a servo motor with a holding brake (optional), add "B" to the end of the model number

"Ct." is added to the end of model No. for coolant center-through specification
 At.*···Aluminium, FC*····Cast Iron, ST*···Steel

Dimensions (mm)




Note: Rotary joint is included in the standard supply for coolant center-through specification

Adjustable spindle nose (option)

Please specify the adjustable spindle nose when ordering your servo drill.

Sugino supplies adjustable spindle noses other than those shown below, upon request.


Applicable selfeeder	Fig. No.	Spindle nose model No.
SSM4-1673、SSM4-1636	1	KH-16A
SSM4-1618, SSM4-1608	2	KH-22A



Notes: Spindle noses KH-A model is applicable to the quick change stub holder of KH-A model of NT Tool Co.,Ltd.

Electric system diagram

All the electric parts supplied as standard are indicated in box. The purchaser is responsible for and needs to have the other cables and equipment.




Notes1. The feed controller and the spindle inverter are standard accessories.


- 2. The programming console and touch panel is optionally available. The attached cable is 3m long.

 3. Programming from a computer is possible using a (§ PC cable A. In such case, a dedicated computer monitoring software is required.
- Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port.

Controller for feed motor UC-81A



Inverter for spindle motor E100-007LFR2



Specification of signal

1/0	Signal	Contents			
Analog	ORD	Command for spindle speed			
Output	СОМ	Ground of command for spindle speed			
	INO	Emergency stop			
	IN1	Manual coolant ON/OFF			
	IN2	Power "ON"			
	IN3	Machine zero return			
	IN4	Single step			
	IN5	Spindle alarm			
	IN6	JOG+			
	IN7	JOG-			
	IN8	Forward side OT			
	IN9	Backward side OT (Combine with origin LS)			
 #1	NC	No contact terminal			
Input	IN10	Alarm clear			
	IN11	EXT/MANUAL			
	IN12	Manual spindle ON/OFF			
	IN13	Program 1			
	IN14	Program 2			
	IN15	Program 4			
IN16 IN17		Program 8			
		Program 10			
	IN18	Program 20			
	IN19	Program 40			

1/0	Signal	Contents
100	OUT0	RDY
	OUT1	Cycle run
	OUT2	Program end
	OUT3	Origin
#2 Output	OUT4	Spindle ON
Output	OUT5	Ready for single step
	OUT6	Coolant ON
	OUT7	Forward sideON
	OUT8	Alarm

※2 Voltage: DC24V, Electric current: 90mA



Selfeeder Mechatric



High-precision and high-rigidity unit which uses united structure of spindle unit and slide table. It offers high-efficient deep hole drilling because of 300mm long stroke and coolant center-through system.


Specification Chart

Specs.	Coindle one	ad (na laad)			May	Drilling	cizo	to Blek	Maria Land			Devilat		
Specs.	opinule spe	eu (no noau)	Chuck type	Chucking				Charles	Spindle	Feed	Thomas	Rapid	Cutting	Maight
	50Hz		(Collet chuck)	capacity	AL* (ADC)	FC* (FC200)	ST* (S45C)	Stroke	motor	motor	Inrust	approach speed	speed	weight
Model	mi	n ⁻¹		mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	kg
SSM5-2641BCL	4,100	4,900			8	4	4		0.0					
SSM5-2634BCL	3,400	4,000			9	5	5		2.2 Induction motor					
SSM5-2625BCL	2,500	3,000	*		12	6	6							
SSM5-2621BCL	2,100	2,500			10	5	5			2.7				
SSM5-2617BCL	1,700	2,000.	ER40	Max.26	12	6	6	Max. 300	1.5	AC servo	5,000	Max. 300	Max. 16.7	230
SSM5-2611BCL	1,100	1,300			16	9	8		Induction motor	motor		000	10.7	
SSM5-2607BCL	700	850			19	14	12.5							
SSM5-2604BCL	400	480			19	15	13.5		0.75					
SSM5-2602BCL	220	260			24	21	19		Induction motor					

- Notes 1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)
 - 2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.

 3. The power voltage of the feed controller and main spindle inverter is a 3-phase 200V AC±10%, 50/60Hz.
 - Holding brake is attached to the feed motor.
 - 5. Coolant center-through is used for SSM5 as standard specification. Please direct if you do not need it. 6. AL*---Aluminium, FC*---Cast Iron, ST*---Steel

Dimensions (mm)




Note: Rotary joint attaches to SSM5 as standard

Adjustable spindle nose (option)

Please specify the adjustable spindle nose when ordering your servo drill.

Sugino supplies adjustable spindle noses other than those shown below, upon request.


Applicable selfeeder	Fig. No.	Spindle nose model No.
SSM5-26**BCL	1	KH-32EC



Notes: Spindle noses KH-EC model is applicable to the quick change stub holder of KH-EC model of NT Tool Co.,Ltd.

Electric system diagram


All the electric parts supplied as standard are indicated in The purchaser is responsible for and needs to have the other cables and equipment.



Notes1. The feed controller is standard accessories.

- 2. The programming console and touch panel is optionally available. The attached cable is 3m long.
- 3. Programming from a computer is possible using a @ PC cable A. In such case, a dedicated computer monitoring software is required. Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port

Controller for feed motor UC-83A



Specification of signal

1/0	Signal	Contents
	INO	Emergency stop
	IN1	Manual coolant ON/OFF
	IN2	Power "ON"
	IN3	Machine zero return
	IN4	Single step
	IN5	Spindle alarm
	IN6	JOG+
	IN7	JOG-
	IN8	Forward side OT
	IN9	Backward side OT (Combine with origin LS)
 #1	NC	No contact terminal
Input	IN10	Alarm clear
	IN11	EXT/MANUAL
	IN12	Manual spindle ON/OFF
	IN13	Program 1
	IN14	Program 2
	IN15	Program 4
	IN16	Program 8
	IN17	Program 10
	IN18	Program 20
	IN19	Program 40
	IN20	Program 80

1/0	Signal	Contents
	OUT0	RDY
	OUT1	Cycle run
	OUT2	Program end
	OUT3	Origin
#2 Output	OUT4	Spindle ON
Output	OUT5	Ready for single step
	OUT6	Coolant ON
	OUT7	Forward sideON
	OUT8	Alarm

*1 Voltage: DC24V, Electric current: 10mA

φ14

Sugino Machine Limited

Selfeeder Mechatric





Most suitable unit for doing small diameter/deep hole drilling or high-precision drilling with carbide tooling. Easy unit replacement on operations originally utilizing Selfeeder "Electric" types because it uses the same "circular body style".

Specification Chart


Specs.	Spindle spe	ed (no load)	Chuck type	Chucking	Max.	Drilling	size		Spindle	Feed		Rapid	Cutting	
	50Hz	60Hz	(Collet chuck)	capacity	AL* (ADC)	FC* (FC200)	ST* (S45C)	Stroke	motor	motor	Thrust	approach speed	Cutting speed	Weight
Model	mi	n ⁻¹		mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	kg
MS3P-3075LLZ	7.500	9,000			3	1.5	1.5							
MS3P-3060LLZ	6,000	7,200	ED11	0.5~7	4	1.5	1.5		0.35					
MS3P-6049LLZ	4,900	5,900	ER11	0.5~7	5	2	2		2P			0 Max. 200		34
MS3P-6034LLZ	3,400	4,100			7	3	3		Induction				Max. 16.7	34
MS3P-1326LLZ	2,600	3,200			7.5	3.5	3.5	150	motor	0.4 AC servo motor				
MS3P-1318LLZ	1,800	2,200			8.5	5	4				1,760			
MS3P-1314LLZ	1,400	1,700			9.5	6	6							
MS3P-1310LLZ	1,000	1,200	ER20	0.5~13	10	8	7		0.35					
MS3P-1307LLZ	700	800	,10		12	9	8		6P Induction					35
MS3P-1306LLZ	600	700			13.5	10.5	9	1	motor					
MS3P-1305LLZ	500	600			14	12	10							

Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

The drilling capacity shown above is for a depth equivalent to the drill diameter times two.
 The power voltage of the main spindle motor is a 3-phase 200V AC±10%, 50/60Hz. (Feeding axis controller is single-phase.)

4. In the case of a servo motor with a holding brake (optional), add "B" to the end of the model number. 5. AL*...Aluminium, FC*...Cast Iron, ST*...Steel

Dimensions (mm)



Selfeeder Mechatric



High-power model which has a 3.7kW spindle motor and 7,800N thrust. It can do facing, end-milling and 28mm diameter drilling operations into steel material.

Specification Chart


The second second														
Specs.	Spindle spe	ed (no load)	Chuck type	Chucking	Max.	Drilling	size		Cnindle	Food	1,107	Rapid	Cutting	300
	50Hz	60Hz	(Collet chuck)	capacity	AL*	FC* (FC200)	ST* (S45C)	Stroke	Spindle motor	Feed	Thrust	approach speed	Cutting speed	Weight
Model	mi	n-1	_	mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	kg
MS7-3229	2,900	3,500			11	4	3		3.7			Max. 298	Max. 16.7	270
MS7-3222	2,200	2,700			13	5	4							
MS7-3215	1,500	1,800			17	7	6			2.7				
MS7-3210	1,000	1,200	ER32	1.0~20	20	14	12	200	22	AC servo	7,800			
MS7-3206	650	800			25	19	16		2.2 6P Induction motor	motor				
MS7-3205	500	600			31	24	21							
MS7-3203	340	410			40	32	28							

Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

The drilling capacity shown above is for a depth equivalent to the drill diameter times two.
 The power voltage of the feed controller and main spindle motor is a 3-phase 200V AC±10%, 50/60Hz.

4. In the case of a servo motor with a holding brake (optional), add "B" to the end of the model numbe 5. AL*···Aluminium, FC*···Cast Iron, ST*···Steel


Dimensions (mm)



(mm)

φ12

Sugino Machine Limited



- Notes1. Operation panel, the programming console and touch panel is optionally available. The attached cable is 3m long.
 - 2. Programming from a computer is possible using a PC monitor soft cable. In such case, a dedicated computer monitoring software is required. Working environment: OS Windows 95/98/XP (The mode setting is necessary), Communication interface RS232C-port.
 - 3. Turret rotation can operate from operation panel only. It is impossible for doing turret rotation from programming console, pouch panel and PC monitor software

Operation par	nel and Con	troller	
Dimensions(mm)			
Operation panel OB-	11 Controller	UC-121 (for UC-122 (for	SSV3) SSV4)
350 260	117	600	
Connector for operation panel connection	Circuit breaker for NFB1 Digita	I switch	700
40 230	40 Cable correction point	520	150
	4.413	A Enlargement	P
		Tunet No. Program No. Internation Inter	
	SUCINO	Turet No. Program No.	13
	A 1111	Just No. Process Tunt No. Process	15

1/0 Signal Contents Power "ON" X110 Machine zero return Emergency stop Alarm clear * 1 X114 Selfeeder ON Turret Indexing X116 Spare X117 Spare Y50 All origin position Y51 Selfeeder Origin Turret cam Origin *2 Program end Output Alarm Y55 Run Y56 Spare Spare External I/O power DC24V OV External I/O power 0V

Specification of signal

¾1 Voltage: DC24V±10%, Electric current: less or equal 7mA #2 Voltage: DC24V, Electric current: less or equal 100mA



CNC Turret Head



Compact sized turret which uses a Selfeeder "Varimec" as a drive unit. It has a tool change function so 1 machine can do 4 types of operations. Also it is useful for using by "automatic drilling machine style with tool change system".

Specification Chart

Specs.	Spindle spee	ed (no load)	Chuck tuno	Chucking capacity	Max. Drilling size				Spindle	Food		Rapid		Indexir	ng time	
	50Hz				AL^	FC* (FC200)	ST* (S45C)	Stroke		motor	Thrust	approach speed	speed	50Hz	60Hz	Weight
Model	mii	n-1		mm	mm	mm	mm	mm	kW	kW	N	mm/sec	mm/sec	sec	sec	kg
4TH3S + SSV3-7100THB	1,000~	7,000			6.5	5	4	Max. 200	0.4	O.4 AC servo motor	1,660	Max.		0.9	0.8	73
4TH3S + SSV3-1626THB	265~	2,650	Stub holder [KH-20E] NT tool]	2.6~9.0	12	9	8		motor			200	Max. 16.7			
4TH3S + SSV4-2070THB	1,000~	7,000	*		9	8	7 .	Max. 250	1.0 DC brushless motor	1.2 AC servo motor	4,600	Max. 220				110


Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.

Indexing time is the time for turret rotation. It does not including the time of spindle start and stop.
 When you install this turret head into SSV3-7100THB, please set "under 7,000min⁻¹" for spindle rotation speed.

5. Holding brake is attached to the feed motor.
6. AL*···Aluminium, FC*···Cast Iron, ST*···Steel

Dimensions (mm)



Note: Air must be supplied to cool the spindle motor as to protect the spindle bearings. Be sure to supply clean dry air.

φ20


Max. Tapping size (mm)



CNC Turret Head







Designed to integratge onto space-saving and high-efficient production machines, the versatile it can combine plural kinds of process like facing, drilling, chamfering, tapping and other kinds of processing.

Specification Chart

10.77															
Specs.	Spindle spe	ed (no load)	Chuck tuno	Chucking	Max. Dri	lling/Tapp	ping size	Spindle	Feed		Rapid	Indexing time			
	50Hz			capacity	AL*	FC* (FC200)	01	Stroke		motor	Thrust	approach speed	50Hz	60Hz	Weight
Model	mi	n ⁻¹	-	mm	mm	mm	mm	mm	kW	kW	Ν	mm/sec	sec	sec	kg
4TH5-1660	4TH5-1660 Max.6,000	2 000	10		14	11	9.5	Max.	2.0	1.2 AC servo			1.2	1.0	260
41115-1660	IVIAX.	5,000	Stub holder		M10	М8	М8				Max.	Max.	1.2	1.0	200
ATUE 1612	Mov	1 200	[KH-25E] NT tool]	3.6~16.0	20	15	13	200	motor	motor	1,960	500	1.5	1.0	200
4105-1012	TH5-1612 Max.1,200	Max.1,200			M16	M12	M12						1.5	1.2	280


Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed. (cutting speed)

2. The upper row of the maximum drilling/tapping capacity section shows the maximum drilling capacity. And lower row shows the maximum tapping capacity.

3. The drilling capacity shown above is for a depth equivalent to the drill diameter times two. A spiral type or point type tapping tool is used for the tapping capacity section.

Tapping capacities are conditional on the depth of tapping being limited to 1.5 times the tap diameter 4. Holding brake is attached to the feed motor. 5. AL*···Aluminium, FC*···Cast Iron, ST*···Steel

Dimensions (mm)




Note1. For protecting the inside structure, please input dry air for air-purge from Rc1/8.

2. Parenthesized numbers are showing the dimensions of 4TH5-1612.


Electric system diagram All the electric parts supplied as standard are indicated in box. The purchaser is responsible for and needs to have the other cables and equipment. ① 4-axis Turret head 4TH5 3 Signaling cable for feed motor Power cable for feed motor. ⑤ LS cable for feed motor 6 Power cable for spindle motor · ③ Signaling cable for spindle motor · · 5m ® Cable for fan of spindle motor · 9 LS cable for turret rotation -10 Motor cable for turret rotation · · · · 5m Teaching unit (option) Operation panel (OB-02, Attached cable 3m) Cable length 3m Laptop compute

Operation panel and Controller



Controller UC-110

Dimensions(mm)



Specification of Controller

	lodel No.	NCBOY-200						
Con	trolled axes	1 axis (Z axis) + S axis						
		Least input increment : 0.001mm						
		Least command increment : 0.001mm						
	Input commands	Max. programmable dimension: 999999999999999999999999999999999999						
		Decimal point input.						
		Cutting feed rate : F mm/min direct commar						
		G00 Positioning G31 Skip function						
	O formation	GO1 Liner interpolation G53 Command in machine coordinates						
	G function (Any other G code	G04 Dwell G90 Absolute comma						
	can not accept	G09 Positioning check G91 Incremental commar						
	except right G code)	G11 Time-fixed feeding G92 Coordinate system setti						
*1		G28 Automatic return to reference point						
NC Program	M function (For external output)	M50~M57 : Codes for customer.						
Поттовган	Special function	RTAPX Tapping.						
	S function	Command spindle speed, rotation start and stop						
	T function							
		Command assignment turret No. and turret index sta						
	Various calculate function	○ (Available in NC program.)						
	Confirm NC status, Setting or reference I/O parameter	(Available only in NC program.)						
	Use of register	○ (Available for coordinate address.)						
	Macro command	×						
	Canned cycle	×						
	Tool life management	×						
	Operation panel	Using in case of manual operation.						
Description for	*1	Inputting, reference and changing the NC progra						
components	Teaching unit	·Reference and Changing the parameter of NC program and amplifier.						
	PC software	·Monitoring the operating conditions of NC program and amp						
		Machine zero return.						
		Servo motor ON.						
	*2	Cycle run.						
	Output signal	Program end.						
	1000 Julio 10 0 0000	Alarm						
		M50~M57 : Codes for customer.						
		Automatic operation start.						
		External emergency stop.						
External		Reset						
I/O signal		Program No.1 (Assign program No.)						
		Program No.2 (Assign program No.)						
	*3	Program No.4 (Assign program No.)						
	Input signal	Program No.8 (Assign program No.)						
	iliput sibilal							
		Program No.10 (Assign program No.)						
		Program No.20 (Assign program No.)						
		Program No.40 (Assign program No.)						
		Program No.80 (Assign program No.)						
	I	M code FIN.						

**2 Voltage : DC24V, current : less or equal 40mA.

Sugino Machine Limited

Sugino's program input system; high-efficiency and easy-operation.

Processing program inputting method (Option)

For controller UC-81A, 82 and 83A, Sugino has 3 options for inputting data, confirming the condition, single unit manual operating, and seeing alarms.



Programming console PC-03B

Key input small sized monitor type Easy operation by touch panel Programming operation from your PC

can set the stroke and spindle rotation speed in a one touch operation. With minimal key strokes and operate CNC programs very easily. quickly input programs.

Attached cable (3m)



Touch panel TP-01

Compact sized and light weight monitor which 5.7inch color type liquid crystal pouch panel. Beginners are also able to produce

Indicate language:

→Japanese, English, Chinese and Korean Attached cable (3m) Back up memory (Option):

> → Compact flash card (32MB) →Compact flash reader writer



monitor soft

Use exclusive type monitor software which can do programming operation from your PC. Special cable for connecting with your PC is required.

Working environment


→OS Windows 95/98/XP (The mode setting is necessary)

Communication interface →RS232C-port



Multi drop connection

By connecting multiple controllers with multi drop cable, programming can be achieved without pulling out cables. (Maximum 10 controllers are connected.)



Process patterns


14 process patterns included in the UC-8* Controller. Simply choose suitable pattern for your processing specification.

	January Salarana
Pattern No.	Function
01	Drilling
02	High-speed deep hole drilling (Step feed drilling)
03	Deep hole drilling (Step feed drilling)
04	Quill pipe drilling (Skip feed drilling)
05	Drilling Counterboring
06	Drilling (with inching feed)
07	High-speed deep hole drilling (with inching feed)
08	Deep hole drilling (with inching feed)
09	Quill pipe drilling (with inching feed)
10	Drilling Counterboring (with inching feed)
11	Back chamfering
12	Quill pipe multi-step drilling (with inching feed)
13	2-step front/rear chamfering
15	Non-step deep hole drilling

Example of process patterns

Deep hole drilling (Step feed drilling)

Applied for Deep hole drilling, generally referred to as step drilling. Cutting oil delivered to edge of drill bit because the drill bit is pulled out of



Applied to perform Inching feed Cutting feed counterboring after drilling. Also applied to reduce burrs on the rear surface at through hole drilling.

No.05 Drilling Counterboring




No.06 Drilling (with inching feed)

Applied to reduce Inching feed Cutting feed burrs on the both front and rear surface

wwwww

No.09 Quill pipe drilling (with inching feed) for process pattern No.4

when drill biting and through-hole are performed. Helps to reduce burrs.



Additional Sugino products which can achieve high-efficient operations besides Selfeeder servo series.

NC automatic drilling machine Standrill NC

All that is needed for operation on the same day is a connection with the main power supply. This is an NC automatic drilling machine available not only for drilling but also tapping. An optional touch panel allows easy operation of NC programs even if the user is a beginner.



High rigidity spindle motor Varimotor

The same high-rigidity and high-power DC brushless motor and precise angular bearing as the Selfeeder Varimec are utilized. It is compact sized spindle unit and capable of doing heavy cut processing.

Application

- 1. Install into spindle unit for drilling and end-milling operation
- 2. Install into robot for de-burring operation.
- 3. Install into special purpose machine for various cutting operations.



Specification Chart

Specs.	Spindle spe	ed (no load)	Chuck type	Chucking	Ма	x. Drilling s	ize	Spindle motor	
	50Hz	60Hz	(Collet chuck)	capacity	AL* (ADC)	FC* (FC200)	ST* (S45C)	(Max. output)	Weight
Model	mi	n-1	_	mm	mm	mm	mm	kW	kg
SSV2-7200CM	2,000~20,000		ER11MS	0.5~7.0	5	5 4		0.0	4
SSV2-1039CM	390~	3,900	ER16	0.5~10.0	8.5	7.5	6.5	0.9	4
SSV3-7100CM	1.000~	10.000	ER11	0.5~7.0	6.5	5	4		
33 V 3-7 TOOCIVI	1,000	10,000	ER20	0.5~13.0	0.5	5	4	0.4	12
SSV3-1626CM	265~	2.650	ER20	0.5~13.0	12	9	8	0.4	12
33 V 3-10 Z 0 C W	200 -	2,000	ER25	0.5~16.0	12	9	0		
SSV4-2070CM	1,000~	7,000	ER32	1.0~20.0	9	8	7	1.0	0.4
SSV4-2017CM	250~	1,750	Enoz	1.0~20.0	16	15	13	1.0	24
SSV5-2055CM	800~ 5,500		ER32	1.0~20.0	14.5	11.5	9.5	1.0	40
SSV5-2610CM	250~	1,010	ER40	2.0~26.0	25	20.5	18	1.6	43

Notes1. To select your model, refer to the workpiece configurations, material, cutting properties, diameter of the hole, and rotation speed.(cutting speed)

2. The drilling capacity shown above is for a depth equivalent to the drill diameter times two.

 The power voltage is a 3-phase 200V AC±10%, 50/60Hz. 4. For cooling the motor in inside, please input clean dry air into air-inlet.

5. Please take care for not closing the air-outlet for motor cooling by clamp fixture etc. Also please set the air-outlet certainly becomes downward.

6. The leading direction of cable is different from the type of Varimotor. If you need more detailed information, please ask your nearest sales offices.

Dimensions(mm)

